## National Transportation Safety Board NTSB ID: ANC03LA030 Aircraft Registration Number: N1276P FACTUAL REPORT Occurrence Date: 01/30/2003 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone 0330 ΑK 99657 AST Russian Mission Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft

Sightseeing Flight: No Air Medical Transport Flight: Medical Emergency

## Narrative

Cessna

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On January 30, 2003, about 0330 Alaska standard time, a Cessna 208B airplane, N1276P, sustained substantial damage when the airplane's tail impacted the ground during passenger loading at the Russian Mission Airport, Russian Mission, Alaska. The airplane was being operated as an instrument flight rules (IFR) medical patient transfer flight under Title 14, CFR Part 135, by Grant Aviation, Inc. of Anchorage, Alaska. The airline transport pilot, patient, and the three medical attendants were not injured. The intended destination was Bethel, Alaska.

208B

During a telephone conversation with the National Transportation Safety Board (NTSB) investigator-in-charge (IIC), on March 3, an FAA aviation safety inspector from the Anchorage Flight Standards District Office, said he was inspecting maintenance records at Grant Aviation, when he noticed a major airframe repair for unreported damage had been completed on the accident airplane.

During a telephone conversation with the IIC on March 3, the director of operations for the operator said the accident pilot told him that he (the pilot) did not place the tail stand under the tail of the airplane while loading a medical patient at Russian Mission on the morning of the accident. The pilot told him the tail of the airplane went down on the tail tie down ring because too many people were in the aft section of the airplane while loading the patient. The pilot said it was dark, and he did not see the damage to the tail section, and flew the airplane to Bethel.

In a telephone conversation with the IIC on March 5, a mechanic for the operator said the FS 427.88 bulkhead and tie down assembly were replaced due to the damage.

Airplane

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC03LA030

Occurrence Date: 01/30/2003

AVIATION Occ			ccurrence Type: Accident										
Landing Facility/Approach Information													
Airport Name	Airport ID	D: /	Airport Elevati	ion	Run	way Used	ay Used Runway Length			Runw	ay Width		
Russian Mission 9A			9AK2		350 Ft.	MSL							
Runway Surface Type:							·						
Runway Surface Condition:													
Type Instrument Approach: NONE	Ē												
VFR Approach/Landing: None													
Aircraft Information													
Aircraft Manufacturer			1 1	del/Se	eries						Number		
Cessna			20	8B						208B	0852		
Airworthiness Certificate(s): Normal													
Landing Gear Type: Tricycle													
Homebuilt Aircraft? No	No Number of Seats: 10 Certified Max Gross Wt. 8750 LBS Number of E							r of En	Engines: 1				
• • • • • • • • • • • • • • • • • • • •				Engine Manufacturer: Model/Series: Pratt & Whitney Canada PT6A-114A					Rated Pov 675 HP				
- Aircraft Inspection Information													
Type of Last Inspection Date				Date of Last Inspection Time			Time Si	nce Last Insp	ection	Airframe Total Time			
AAIP 12				12/27/2002					86 Hours			2	800 Hours
- Emergency Locator Transmitter (I	ELT) Information												
ELT Installed? Yes	ELT Installed? Yes ELT Operated? No ELT Aided in Locating Accident Site? No												
Owner/Operator Information													
Registered Aircraft Owner	Registered Aircraft Owner  Street Address 4451 Aircraft Drive												
GRANT AVIATION INC			City	City							State		Zip Code
			Stree	Anchorage AK Street Address									99502
Operator of Aircraft					Same as	Reg'	d Aircr	aft Owner					
Same as Reg'd Aircraft Owner				City						State	9	Zip Code	
Operator Does Business As: Grant Aviation Inc.  Operator Designator Code: ENHA													
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s):	Commuter Air Ca	arrier; (	On-dema	and A	ir Taxi								
Operating Certificate:	Operating Certificate: Operator Certificate:												
Regulation Flight Conducted Under	r: Part 135: Air Ta	ıxi & C	ommuter	r	•								
Type of Flight Operation Conducted													
		FACTI	UAL RE	POR'	T - AVIATIO	NC							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC03LA030

Occurrence Date: 01/30/2003

AVIATION Occurrence Type: Accide					cident							
First Pilot Information												
Name	City				State	tate Date of Bir		Age				
On File	On File				On Fil	e   0	n File	40				
I		UIT OIT FIRE						1 10				
Sex: M Seat Occupied:	Pilot	ot Certificate Number: On File										
Certificate(s): Airline Transport												
Airplane Rating(s): Multi-engine Land; Single-engine Land												
Rotorcraft/Glider/LTA: Helicopter												
Instrument Rating(s): Airpla	•											
Instructor Rating(s): Airpla	ane Single-	engine										
3(0)												
Type Rating/Endorsement fo	or Accident/In	cident Aircra	ft? Yes			Current B	ienni	al Flight R	eview?	12/05/2	2002	
Medical Cert.: Class 1	Medica	al Cert. Status	s: Valid Me	dicalno wa	ivers/lim.			Date of La	st Medi	cal Exan	n: 04/06/200	02
							•					
- Flight Time Matrix	ne Matrix  All A/C  This Make     Airplane     Airplane     Airplane     Mult-Engine  Mult-Engine			Night	Instrument ght Actual Simulate		ent Simulated	Roto	orcraft	Glider	Lighter Than Air	
Total Time	9800 3500 5200 3050		600	) 4	110	25	0	200	2			
Pilot In Command(PIC)	8300	3500	5200	1600	600	)						
Instructor												
Last 90 Days	34	34	34		34							
Last 30 Days	5	5	5		5	5						
Last 24 Hours	2	2	2		2	2						
Seatbelt Used? No	Shou	lder Harness	Used? No		Toxi	Toxicology Performed? No Second Pilot? No						
Flight Plan/Itinerary												
Type of Flight Plan Filed: IFI	R											
Departure Point					Stat	State Airport Identifie			er Departure Time			Time Zone
Same as Accident/Incide	nt Location					9AK2						AST
Destination					Stat	State Airport Identifier			r			
Bethel	AK											
Type of Clearance: Unknown												
Type of Airspace: Unknown												
Weather Information												
Source of Briefing: Unknown												
Method of Briefing: Unknown												
	FACTUAL REPORT - AVIATION Page 3											

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC03LA030

Occurrence Date: 01/30/2003

Occurrence Type: Accident

	c1 1 BO.												
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF Elevat	ion	WOF Di	WOF Distance From Accident Site				Direction From Accident Site			
				MOL				NINA		Deg. Mag.			
			l Ft	. MSL	<u> </u>			NM Deg.					
Sky/Lowes	st Cloud Condition: Cle			Ft. A	AGL	Condition of Light: Night/Dark							
Lowest Ce	iling: None	AGL	Visib	Visibility: 10 SM			Alti	Altimeter: "F					
Temperatu	°C	Wind	Wind Direction: Density Altitude:										
Wind Speed: Gusts:					Weather Condtions at Accident Site: Visual Conditions								
Visibility (F	RVR): F	t. Visibility (F	RVV)	SM	Intensity	of Precip	oitation:						
Restriction	s to Visibility: None												
Type of Pr	ecipitation: None												
Accident	Information												
Aircraft Damage: Aircraft Fire: Aircraft Explosion													
Classificati	on:												
- Injury Su	mmary Matrix	Fatal S	erious Mino	or	None	TOTAL							
First Pi	ilot				1		1						
Second	d Pilot												
Studer	nt Pilot												
Flight I	nstructor												
Check	Pilot												
Flight E	Engineer												
Cabin /	Attendants												
Other (	Crew												
Passer	ngers				4		4						
- TOTAL /	ABOARD -				5		5						
Other (	Ground												
- GRANI	O TOTAL -		5 5										

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: ANC03LA030

Occurrence Date: 01/30/2003

Occurrence Type: Accident

			nation

Investigator-In-Charge (IIC)

Lawrence R. Lewis

Additional Persons Participating in This Accident/Incident Investigation:

Bruce Walker Aviation Safety Inspector Anchorage FSDO-03 4510 W. International Airport Road Anchorage, AK 99502